

The State of Utah

Department of Natural Resources

Division of Oil, Gas & Mining

ROBERT L. MORGAN Executive Director

LOWELL P. BRAXTON
Division Director

OLENE S. WALKER Governor

GAYLE F. McKEACHNIE

Lieutenant Governor

Representative	es Present During the Inspection:
OGM	Joe Helfrich Environmental Scientist III
Company	Seth McCourt

Inspection Report

Permit Number:	C0150007			
Inspection Type:	PARTIAL			
Inspection Date:	Wednesday, August 04, 2004			
Start Date/Time:	8/4/2004 10:00:00 AM			
End Date/Time:	8/4/2004 2:00:00 PM			
Last Inspection:	Wednesday, July 14, 2004			

Inspector: Joe Helfrich, Environmental Scientist III

Weather: sunny breezy 85

InspectionID Report Number: 364

Accepted by: whedberg 8/23/2004

Permitee: CONSOLIDATION COAL CO

Operator: CONSOLIDATION COAL CO MID-CONTINENT REGION

Site: **HIDDEN VALLEY MINE**

Address: PO BOX 566, SESSER IL 62884

County: EMERY

Permit Type: PERMANENT COAL PROGRAM

Permit Status: RECLAIMED

Current Acreages

	Phase III	
	Phase II	
6.70	Phase I	
6.70	Total Disturbed	
960.00	Total Permitted	

☐ Federal ✓ Underground
☐ State ☐ Surface

□ County
□ Loadout

✔ Fee
□ Processing

□ Other
□ Reprocessing

Report summary and status for pending enforcement actions, permit conditions, Divison Orders, and amendments:

The purpose of this site visit was to conduct a partial inspection of the Hidden Valley mine. There are no pending amendments, permit conditions, or compliance issues.

Inspector's Signature

Date

Monday, August 09, 2004

Joe Helfrich, Environmental Scientist III Inspector ID Number: 1

Note: This inspection report does not constitute an affidavit of compliance with the regulatory program of the Division of Oil, Gas and Mining.

1594 West North Temple, Suite 1210, PO Box 145801, Salt Lake City, UT 84114-5801 telephone (801) 538-5340 facsimile (801) 359-3940 TTY (801) 538-7223 www.ogm.utah.gov



Permit Number: C0150007 Inspection Type: PARTIAL

Inspection Date: Wednesday, August 04, 2004

Page 2 of 3

REVIEW OF PERMIT, PERFORMANCE STANDARDS PERMIT CONDITION REQUIREMENTS

- 1. Substantiate the elements on this inspection by checking the appropriate performance standard.
 - a. For COMPLETE inspections provide narrative justification for any elements not fully inspected unless element is not appropriate to the site, in which case check Not Applicable.
 - b. For PARTIAL inspections check only the elements evaluated.
- Document any noncompliance situation by reference the NOV issued at the appropriate performance standard listed below.
 Reference any narratives written in conjunction with this inspection at the appropriate performance standard listed below.
- 4. Provide a brief status report for all pending enforcement actions, permit conditions, Divison Orders, and amendments.

		Evaluated	Not Applicable	Comment	Enforcement
1.	Permits, Change, Transfer, Renewal, Sale	✓		✓	
2.	Signs and Markers	V		✓	
3.	Topsoil				
4.a	Hydrologic Balance: Diversions				
4.b	Hydrologic Balance: Sediment Ponds and Impoundments				
4.c	Hydrologic Balance: Other Sediment Control Measures	✓		✓	
4.d	Hydrologic Balance: Water Monitoring				
4.e	Hydrologic Balance: Effluent Limitations	✓		Y	
5.	Explosives				
6.	Disposal of Excess Spoil, Fills, Benches				
7.	Coal Mine Waste, Refuse Piles, Impoundments				
8.	Noncoal Waste				
9.	Protection of Fish, Wildlife and Related Environmental Issues				
10.	Slides and Other Damage				
11.	Contemporaneous Reclamation				
12.	Backfilling And Grading				
13.	Revegetation	✓		✓	
14.	Subsidence Control				
15.	Cessation of Operations				
16.a	Roads: Construction, Maintenance, Surfacing				
16.b	Roads: Drainage Controls				
17.	Other Transportation Facilities				
18.	Support Facilities, Utility Installations				
19.	AVS Check				
20.	Air Quality Permit				
21.	Bonding and Insurance				
22.	Other				

Permit Number: C0150007 Inspection Type: PARTIAL

Inspection Date: Wednesday, August 04, 2004

Page 3 of 3

1. Permits, Change, Transfer, Renewal, Sale

The reclamation permit was renewed on January 29, 2002 and expires January 30, 2007.

2. Signs and Markers

A sign containing the required information was posted at the entrance to the access road.

4.c Hydrologic Balance: Other Sediment Control Measures

Silt fences are the primary sediment control along with water bars and pocking on portions of the reclaimed area. According to the mine personnel, the reclaimed area was the subject of several rain storms during the past few days. The soil was still moist and lvie creek was laiden with sediment. The silt fences pocking and water bars effectively contained the runoff from the storms. The upper portion of the silt fence below the "A" seam could be restrung in several places.

4.e Hydrologic Balance: Effluent Limitations

lvie creek was flowing at about 25 GPM. The high water mark was two feet above the current flow level at the time of the inspection.

13. Revegetation

Photos of the reclaimed site were taken during this inspection. They might be located in the M directory under images 08042004 for this mine.